Department: Water Utilities Employee/Workgroup: Service

Equipment Name Backhoe (393)

Person Monitoring: Scott Mosley Date: 05/19/04 Time: 0620

Monitoring Results (dBA)

Idle: -- Run: -- Operational/Engaged: 87.9 Transport: --

Exceed TWA of 85 dBA: NO Exceed Impact Noise of 140 dBA: --

Hearing Protection Required: YES Signage Required: YES

Department: Water Utilities Employee/Workgroup: Service

Equipment Name Bobcat

Person Monitoring: Scott Mosley Date: 05/19/04 Time: 0625

Monitoring Results (dBA)

Idle: -- Run: -- Operational/Engaged: 104 Transport: --

Exceed TWA of 85 dBA: YES Exceed Impact Noise of 140 dBA: --

Hearing Protection Required: YES Signage Required: YES

Department: Water Utilities Employee/Workgroup: Service

Equipment Name Crane Truck

Person Monitoring: Scott Mosley Date: 05/19/04 Time: 0630

Monitoring Results (dBA)

Idle: -- Run: -- Operational/Engaged: 99.7 Transport: --

Exceed TWA of 85 dBA: NO Exceed Impact Noise of 140 dBA: --

Hearing Protection Required: YES Signage Required: YES

Department: Water Utilities Employee/Workgroup: Service

Equipment Name Sewer Hydro Vac

Person Monitoring: Scott Mosley Date: 05/19/04 Time: 0635

Monitoring Results (dBA)

Idle: 88.6 Run: -- Operational/Engaged: 95.6 Transport: --

Exceed TWA of 85 dBA: YES Exceed Impact Noise of 140 dBA: --

Hearing Protection Required: YES Signage Required: YES

Department: Water Utilities Employee/Workgroup: Service

Equipment Name Concrete Saw

Person Monitoring: Scott Mosley Date: 05/19/04 Time: 0640

Monitoring Results (dBA)

Idle: -- Run: -- Operational/Engaged: 101.3 Transport: --

Exceed TWA of 85 dBA: YES Exceed Impact Noise of 140 dBA: --

Hearing Protection Required: YES Signage Required: YES

Department: Water Utilities Employee/Workgroup: Service

Equipment Name Cut Off Saw

Person Monitoring: Scott Mosley Date: 05/19/04 Time: 0640

Monitoring Results (dBA)

Idle: -- Run: -- Operational/Engaged: 110 Transport: --

Exceed TWA of 85 dBA: YES Exceed Impact Noise of 140 dBA: --

Hearing Protection Required: YES Signage Required: YES

Department: Water Utilities Employee/Workgroup: Service

Equipment Name Jack Hammer

Person Monitoring: Scott Mosley Date: 5/19/04 Time: 0645

Monitoring Results (dBA)

Idle: -- Run: -- Operational/Engaged: 112 Transport: --

Exceed TWA of 85 dBA: YES Exceed Impact Noise of 140 dBA: --

Hearing Protection Required: YES Signage Required: YES

Department: Water Utilities Employee/Workgroup: Service

Equipment Name Generator

Person Monitoring: Scott Mosley Date: 08/23/03 Time: 0630

Monitoring Results (dBA)

Idle: -- Run: -- Operational/Engaged: 99.1 Transport: --

Exceed TWA of 85 dBA: YES Exceed Impact Noise of 140 dBA: --

Hearing Protection Required: YES Signage Required: YES

Department: Water Utilities Employee/Workgroup: Service

Equipment Name Compressor (1030)

Person Monitoring: Scott Mosley Date: 05/19/04 Time: 0645

Monitoring Results (dBA)

Idle: -- Run: -- Operational/Engaged: 87.9 Air Relief: 113

Exceed TWA of 85 dBA: YES Exceed Impact Noise of 140 dBA: --

Hearing Protection Required: YES Signage Required: YES

Department: Water Utilities Employee/Workgroup: Service

Equipment Name Water Pump

Person Monitoring: Scott Mosley Date: 05/19/04 Time: 0650

Monitoring Results (dBA)

Idle: -- Run: -- Operational/Engaged: 81 Transport: --

Exceed TWA of 85 dBA: NO Exceed Impact Noise of 140 dBA: --

Hearing Protection Required: NO Signage Required: NO

Department: Water Utilities Employee/Workgroup: Service

Equipment Name Tapping Machines (Air Compresor)

Person Monitoring: Scott Mosley Date: 05/19/04 Time: 0655

Monitoring Results (dBA)

Idle: -- Run: -- Operational/Engaged: 87.9 Transport: --

Exceed TWA of 85 dBA: NO Exceed Impact Noise of 140 dBA: --

Hearing Protection Required: YES Signage Required: YES

Department: Water Utilities Employee/Workgroup: Service

Equipment Name Cement Mixer (Truck 190)

Person Monitoring: Scott Mosley Date: 05/19/04 Time: 0700

Monitoring Results (dBA)

Idle: 88 Run: -- Operational/Engaged: 97.1 Transport: --

Exceed TWA of 85 dBA: YES Exceed Impact Noise of 140 dBA: --

Hearing Protection Required: YES Signage Required: YES